



**\*\* Envío Gratis en Península \*\***

## \*\* Informacion de Compuestos y Presiones en Imagenes \*\*

Compound			Surface		
		WORKING TEMPERATURE °C	SMOOTH	MEDIUM	ABRASIVE
Super soft	RA9	20°-60°			
Soft	RA7+	30°-70°			
Medium	RA7	50°-90°			
Hard	RA5	70°-130°			
Rain	RW	20°-60°			

## Pressure info

Compound	Condition			Air temperature (°C)									Pressure (Bar)		
	WET	DAMP	DRY	-5	0	5	10	15	20	25	30	30+	COLD PS START	HOT PS END	
Super soft														1.8	2.0-2.2
Soft														1.8	2.0-2.2
Medium														1.6	2.0-2.3
Hard														1.6	2.0-2.3
Rain														2.0	2.0-2.3

